

**ERRATA SHEET FOR
ANSI/ASHRAE/IES STANDARD 100-2018
Energy Efficiency in Existing Buildings**

June 26, 2024

The corrections listed in this errata sheet apply to ANSI/ASHRAE/IES Standard 100-2018. The first printing is identified on the outside back cover as “Product code: 86299 3/18”.

Page Erratum

69 **E2.2.5.** Revise Section E2.2.5 as shown below.

(Note: Additions are shown in underline and deletions are shown in ~~strikethrough~~.)

E2.2.5 Use high-efficiency fans and pumps; replace or trim impellers of existing ~~fans~~pumps if they have excessive capacity relative to peak demand.